Maryland Historical Trust

Maryland Inventory of Historic Properties Number: F-6-117 Name: Passiness USIS over Flow Cur.								
The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridged received the following determination of eligibly.								
MARYLAND HISTOR								
, 		Eligib						
Criteria:ABCD Considerations:	_A	B _	_c _	_D _	_E_	_F _	_G_	_None
Comments:								
Reviewer, OPS:Anne E. Bruder			Date	:3 .	April 2	2001_		
Reviewer, NR Program:_Peter E. Kurtze			Date	:3	April	2001		

Maryland Historical Trust SHA Bridge No. 10001 Name: Business US Route 15 over Flat Run **Location:** Street/Road Name and Number: Business US Route 15 (Catoctin Mountain Highway) City/Town: Emmitsburg Vicinity X County: Frederick Ownership: X State County Municipal Other This bridge projects over: __Road__Railway_X_Water__Land Is the bridge located within a designated district: __yes_X_no _NR listed district_NR determined eligible district locally designated_other Name of District **Bridge Type:** _Timber Bridge _Beam Bridge_Truss-Covered_Trestle _Timber-and-Concrete _Stone Arch _Metal Truss _Movable Bridge _Swing _Bascule Single Leaf_Bascule Multiple Leaf __Vertical Lift_Retractile_Pontoon ___Metal Girder __Rolled Girder __Rolled Girder Concrete Encased _Plate Girder _Plate Girder Concrete Encased _Metal Suspension _Metal Arch _Metal Cantilever X Concrete X Concrete Arch Concrete Slab Concrete Beam Rigid Frame _Other Type Name_

Describe Setting:

Bridge 10001 carries Business US Route 15 over Flat Run in Frederick County. Business US Route 15 runs north-south over the southern flowing Flat Run. The area immediately adjacent to the bridge has light residential development. The bridge leads into Emmitsburg. The surrounding area has light to moderate housing and limited commercial development.

Describe Superstructure and Substructure:

Bridge 10001 is a single-span filled concrete arch. The length of the bridge is 52 feet and it has a clear span of 50 feet. The spandrel wall has a 2-inch cove molding around the arch. The spandrel walls are approximately 9 feet high and 15 feet wide at their widest point. The abutments are approximately 24 feet wide and 8 feet high. There is a clear roadway width of 24 feet, with an overall width of 27 feet 4 inches. According to a 1997 inspection report, the bridge is in fair condition with a sufficiency rating of 69.7.

The parapets are original. The builders used a closed parapet design. This reinforced concrete railing consists of vertical posts securely fastened by dowels to the structure, horizontal rails, and solid panels that fill the space between the posts and railings. The posts and rails were built in place. Expansion joints separate the panels. The parapets are 52 feet long and three feet high with a 6-inch cap across both the eastern and western sides of the bridge. At the end of each parapet is an 8-foot section with incised panels 1-inch thick. The parapets have light scaling over the entire parapet length. Several sections have small and medium areas of spalling with exposed and rusting reinforcement bars. There is a slight misalignment of the parapet cap. A few fine vertical cracks have light efflorescence.

Discuss Major Alterations:

There have been no major alterations to this structure. A large portion of the bridge surface has been patched.

When Built? 1927
Why Built? Widening of US Route 15
Who Built? State Roads Commission

Who Designed? State Roads Commission

Why Altered? Safety concerns.

Was this bridge built as part of an organized bridge building campaign? No, this bridge was not built as part of an organized bridge building campaign.

Surveyor Analysis:

This bridge may have NR significance for association with:

XA Events B Person XC Engineering/Architectural

This bridge was determined eligible by the Interagency Review Committee in February 1996.

Was this bridge constructed in response to significant events in Maryland or local history?

Yes, this bridge was built in 1927 following the completion of the widening of the route between Frederick and Emmitsburg. US Route 15 was part of a statewide road-widening project. The State Roads Commission used new technologies, such as concrete shoulders on macadam roads, to make it easier to bank and widen roads to eliminate curves and bring the older roads into alignment with the requirements of the time.

Is the bridge located in an area that may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

No this bridge is not located in an area of which is eligible for historic designation.

Is the bridge a significant example of its type?

Yes, Bridge 10001 is a significant example of the State Roads Commission's efforts from 1910 to 1945 to eliminate dangerous geometric alignments. The development of standardized plans helped to facilitate this process.

Does the bridge retain integrity of the important elements described in the Context Addendum?

Yes, this bridge retains integrity of its character defining elements. Although some repairs were made to the wingwalls, the barrel, the spandrel walls, the parapets, and the abutments, all are original and have only moderate deterioration.

Should this bridge be given further study before significance analysis is made and why?

No	this	bridge	should	not be	given	further	study.
----	------	--------	--------	--------	-------	---------	--------

Bibliography:	E	3i	b	li	ogr	ap	hy:
---------------	---	----	---	----	-----	----	-----


County inspection/bridge files	SHA inspection/bridge files	X	
Other (list):			

Surveyor:

Name: Stacie Y. Webb Date: September 1995

Organization: State Highway Admin. Telephone: (410) 545-8559

Address: 707 N. Calvert Street, Baltimore, Maryland Edited by P.A.C. Spero & Company, December 1997





Inventory	#	F-6-117

inventory	# _	г	- (P- (1)	_
NT100	/51	_	1150	

Name 10001 - USISB OVER FLAT RUN

Location of Negative __SAA

Description APPROACH NORTH

County/State FREDERICK COUNTY/MD Name of Photographer FRANK JULIAND
Date 295



Inventory #	F-6-117
-------------	---------

TITYCIT	ory π _		-	11/	_
	_				
Name	Innal	- 1	16	10	
IVALLE		- 4	1 %	1	

Name 10001 - US ISB OVER ELAT RUN

Date _ 7/95

Location of Negative _SHA

Description APPROACH SOUTH

- County/State FREDERICK COUNTY/MD Name of Photographer FRANK JULIANO



	11	,	/	,,,,,,
Inventory	Ħ	1	10-	(U_{i})

Invento	ry	#	<i> </i>	10-1	17
Name l	DI)	0	1-	us	15

County/State FREDERICK COUNTY/MD

Date 2193

BOVER FLAT RUN

Location of Negative _ SHA

Name of Photographer FRANK JULIANO

Description EVEVATION WOKING EAST



Inventory	#	F-6-117	
HIVEHUOI V	11	1 6-11	

Name 10001-US ISB OVER FLAT RUN County/State FREDERICK COUNTY/MO
Name of Photographer FRANK JULIANO

Date 2195

Description EVEVATION LUDKING WEST

Location of Negative SHA